



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Report Number: 21-05-01525

Received Date: 05/11/2021
Reported Date: 06/01/2021
Sampled By: Christine Schultz
Tech Certification #:

Project/Test Address: 2020L-157.3; North Park Junior High; 160 Passaic Ave; Lockport, NY 14094

Client Number:
33-5980

Fax Number:
716-312-8092

Laboratory Results

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-05-01525-001	157.3-1A	04/29/2021	FOUNTAIN OUTSIDE ROOM 226	<1.00	05/28/2021	
21-05-01525-002	157.3-1B	04/29/2021	FOUNTAIN OUTSIDE ROOM 226	<1.00	05/28/2021	
21-05-01525-003	157.3-2A	04/29/2021	FOUNTAIN OUTSIDE ROOM 254	<1.00	05/28/2021	
21-05-01525-004	157.3-2B	04/29/2021	FOUNTAIN OUTSIDE ROOM 254	<1.00	05/28/2021	
21-05-01525-005	157.3-3	04/29/2021	FOUNTAIN OUTSIDE ROOM 250	1.90	05/28/2021	
21-05-01525-006	157.3-4	04/29/2021	FACULTY ROOM 247 WOMENS LAV	<1.00	05/28/2021	
21-05-01525-007	157.3-5	04/29/2021	FACULTY ROOM 247 MENS LAV	<1.00	05/28/2021	
21-05-01525-008	157.3-6	04/29/2021	HOME EC 203	8.05	05/28/2021	
21-05-01525-009	157.3-7	04/29/2021	HOME EC LAUNDRY ROOM	20.8	05/28/2021	
21-05-01525-010	157.3-8	04/29/2021	HOME EC SEWING 202	5.09	05/28/2021	
21-05-01525-011	157.3-9	04/29/2021	HOME EC 201 KITCHEN SINK 1	1.69	05/28/2021	
21-05-01525-012	157.3-10	04/29/2021	HOME EC 201 KITCHEN SINK 2	1.28	05/28/2021	
21-05-01525-013	157.3-11	04/29/2021	HOME EC KITCHEN 201 SINK 3	1.37	05/28/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-05-01525

Project/Test Address: 2020L-157.3; North Park Junior High; 160 Passaic Ave;
Lockport, NY 14094

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-05-01525-014	157.3-12	04/29/2021	HOME EC KITCHEN 201 SINK 5	1.49	05/28/2021	
21-05-01525-015	157.3-13	04/29/2021	BOYS LOCKER ROOM LEFT FOUNTAIN	1.00	05/28/2021	
21-05-01525-016	157.3-14A	04/29/2021	BOYS LOCKER ROOM RIGHT FOUNTAIN	1.12	05/28/2021	
21-05-01525-017	157.3-14B	04/29/2021	BOYS LOCKER ROOM RIGHT FOUNTAIN	1.15	05/28/2021	
21-05-01525-018	157.3-15	04/29/2021	AUXILIARY GYM OFFICE SINK	9.60	05/28/2021	
21-05-01525-019	157.3-18	04/29/2021	GIRLS LOCKER ROOM LEFT FOUNTAIN	1.06	05/28/2021	
21-05-01525-020	157.3-19A	04/29/2021	GIRLS LOCKER ROOM RIGHT FOUNTAIN	1.11	05/28/2021	
21-05-01525-021	157.3-19B	04/29/2021	GIRLS LOCKER ROOM RIGHT FOUNTAIN	1.21	05/28/2021	
21-05-01525-022	157.3-20A	04/29/2021	NURSE OFFICE FOUNTAIN	<1.00	05/28/2021	
21-05-01525-023	157.3-20B	04/29/2021	NURSE OFFICE FOUNTAIN	<1.00	05/28/2021	
21-05-01525-024	157.3-21	04/29/2021	MAIN OFFICE KITCHENETTE	2.18	05/28/2021	
21-05-01525-025	157.3-22	04/29/2021	MAIN OFFICE LAV	<1.00	05/28/2021	
21-05-01525-026	157.3-23	04/29/2021	LAV OUTSIDE ROOM 112	5.97	05/28/2021	
21-05-01525-027	157.3-25A	04/29/2021	INDUSTRIAL ARTS ROOM 102 FOUNTAIN	<1.00	05/28/2021	
21-05-01525-028	157.3-25B	04/29/2021	INDUSTRIAL ARTS ROOM 102 FOUNTAIN	<1.00	05/28/2021	
21-05-01525-029	157.3-26A	04/29/2021	INDUSTRIAL ARTS ROOM 101 FOUNTAIN	<1.00	05/28/2021	
21-05-01525-030	157.3-26B	04/29/2021	INDUSTRIAL ARTS ROOM 101 FOUNTAIN	<1.00	05/28/2021	
21-05-01525-031	157.3-29	04/29/2021	BAND ROOM 174 OFFICE	<1.00	05/28/2021	
21-05-01525-032	157.3-30A	04/29/2021	FOUNTAIN OUTSIDE ROOM 124	<1.00	05/28/2021	
21-05-01525-033	157.3-30B	04/29/2021	FOUNTAIN OUTSIDE ROOM 124	<1.00	05/28/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-05-01525

Project/Test Address: 2020L-157.3; North Park Junior High; 160 Passaic Ave;
Lockport, NY 14094

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-05-01525-034	157.3-31	04/29/2021	LADIES STAFF LAV OUTSIDE COURTYARD LEFT	11.5	05/28/2021	
21-05-01525-035	157.3-32	04/29/2021	LADIES STAFF LAV OUTSIDE COURTYARD RIGHT	2.25	05/28/2021	
21-05-01525-036	157.3-33	04/29/2021	SOCIAL WORKER OFFICE BY COURTYARD LAV	40.6	05/28/2021	
21-05-01525-037	157.3-36	04/29/2021	KITCHEN CENTER PREP SINK 2 BAY	<1.00	05/28/2021	
21-05-01525-038	157.3-37	04/29/2021	KITCHEN DISH ROOM SINGLE BAY	1.95	05/28/2021	
21-05-01525-039	157.3-38	04/29/2021	KITCHEN DISH ROOM 2 BAY RIGHT	2.00	05/28/2021	
21-05-01525-040	157.3-39	04/29/2021	KITCHEN REAR KITCHENETTE	<1.00	05/28/2021	
21-05-01525-041	157.3-41	04/29/2021	KITCHEN REAR KETTLE FILL	1.58	05/28/2021	
21-05-01525-042	157.3-42	04/29/2021	KITCHEN FACULTY LEFT LAV	<1.00	05/28/2021	
21-05-01525-043	157.3-43	04/29/2021	KITCHEN FACULTY RIGHT LAV	<1.00	05/28/2021	

Method: EPA 200.8

Analyst: Anthony Dee

Accreditation #: NY 11714

Reviewed By Authorized Signatory: *Melissa Kanode*

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-157.3

Client: Lockport CSD

Contact: Tim Parker

Building: North Park Junior High

Location: 160 Passaic Ave, Lockport, NY 14094

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
157.3-1A	Fountain Outside Room 226	DF	22:40
157.3-1B	Fountain Outside Room 226	DFB	22:42
157.3-2A	Fountain Outside Room 254	DF	22:44
157.3-2B	Fountain Outside Room 254	DFB	22:46
157.3-3	Fountain Outside Room 250	DF	22:48
157.3-4	Faculty Room 247 Womens Lav	S	22:50
157.3-5	Faculty Room 247 Mens Lav	S	22:52
157.3-6	Home Ec 203	S	22:54
157.3-7	Home Ec Laundry Room	S	22:56
157.3-8	Home Ec Sewing 202	S	22:58
157.3-9	Home Ec 201 Kitchen Sink 1	S	23:00
157.3-10	Home Ec 201 Kitchen Sink 2	S	23:02
157.3-11	Home Ec Kitchen 201 Sink 3	S	23:04
157.3-12	Home Ec Kitchen 201 Sink 5	S	23:06
157.3-13	Boys Locker Room Left Fountain	DF	23:08
157.3-14A	Boys Locker Room Right Fountain	DF	23:10
157.3-14B	Boys Locker Room Right Fountain	DFB	23:12
157.3-15	Auxiliary Gym Office Sink	S	23:14

Notes:

Please e-mail lab results to labs@stohlenvironmental.com

☒ If checked, also e-mail results to:

Ehenderson@StohlEnv.com

Sampled By: Christine Schultz Print Name Stohl Env: Christine Schultz Date: 4/29/2021

Relinquished By: E. Henderson Jr. Print Name Stohl Env: Eric Henderson Jr. Date: 5/5/2021


Received (Name / Lab): KTHARRIS K. HARRIS Date: 5-11-21 Time: 1:42 pm

Sample Login (Name / Lab): A. J. J. J. Date: 5/13/21 Time: 9:48 AM

Analysis (Name / Lab): Spring 2021 Date: 5/13/21

QA/QC Review (Name / Lab): M. H. H. Date: 6/1/21

Archived / Released: QA/QC InterLAB Use: Date:



Due Date:
06/08/2021
(Tuesday)
AE



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-157.3

Client: Lockport CSD

Contact: Tim Parker

Building: North Park Junior High

Location: 160 Passaic Ave, Lockport, NY 14094

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10)

X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
157.3-18	Girls Locker Room Left Fountain	DF	23:16
157.3-19A	Girls Locker Room Right Fountain	DF	23:18
157.3-19B	Girls Locker Room Right Fountain	DFB	23:20
157.3-20A	Nurse Office Fountain	DF	23:22
157.3-20B	Nurse Office Fountain	DFB	23:24
157.3-21	Main Office Kitchenette	S	23:26
157.3-22	Main Office Lav	S	23:28
157.3-23	Lav Outside Room 112	S	23:30
157.3-25A	Industrial Arts Room 102 Fountain	DF	23:32
157.3-25B	Industrial Arts Room 102 Fountain	DFB	23:34
157.3-26A	Industrial Arts Room 101 Fountain	DF	23:36
157.3-26B	Industrial Arts Room 101 Fountain	DFB	23:38
157.3-29	Band Room 174 Office	S	23:40
157.3-30A	Fountain Outside Room 124	DF	23:42
157.3-30B	Fountain Outside Room 124	DFB	23:44
157.3-31	Ladies Staff Lav Outside Courtyard Left	S	23:46
157.3-32	Ladies Staff Lav Outside Courtyard Right	S	23:48
157.3-33	Social Worker Office by Courtyard Lav	S	23:50

Notes:

Please e-mail lab results to labs@stohlenv.com

Ehenderson@StohlEnv.com

Sampled By: Christine Schultz Print Name Christine Schultz Date: 4/29/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Date: 5/5/2021

Received (Name / Lab): KT HARRIS K. HARRIS Date: 5.11.21 Time: 1:43 pm

Sample Login (Name / Lab): Traci Borm H. Borm Date: 5/19/21 Time: 7:52 am

Analysis (Name / Lab): Young Ode Date: 5/21/21 Time: 7:14 pm

QA/QC Review (Name / Lab): Michael Date: 6/11/21 Time: 4 pm

Archived / Released: QA/QC InterLAB Use: Date: Time:

